

Embroidery Design Store


To increase and reduces design with pe

We indicate you there on that increasing and reducing patterns **not** whole risk free is!!!!

Both we and Brother believe that a pattern **up to 10% reduced and 20% increased** can become.

Increasing and reducing is easily free do with pe design

- 1 Catch up with and pattern **layout and editing** and click on the pattern so that there stands square for gone.
- 2 Will now with the cursor on the angle stand where vierkantje sit.



hier staan

- 3 Press now on **ctrl test** and chops these pressed and click at the same time on the linker mouse bud.
- 4 If you move now the mouse the pattern becomes larger or smaller and the twinges is adapted automatically To large of the pattern.
- 5 For control you can resistant and then eigenschappen choose the twinges after to look at



For you you start reduce with look at here what stands in the red circle and writes down this
If you are ready with e.g. to reduce then you will see that the half-measure has become smaller and the number of twinges Diminish if this is this way then it well has gone and are possible you are him stich him out.

P.S. at increase the twinges increase in number and the half-measure becomes then of course also larger.